

*
Two SFF cables are required for full-speed operation.